


Cyclone REGISTER 360 PLUS

Registration Report



Aug 31, 2024

Certified by:
Dan Boerner
Special Agent
Ohio BCI



2024-2416 Cleveland Heights

Overall Quality

Error Results for Bundle 1

Setup Count: 21
Link Count: 21


Strength: 23 %
Overlap: 3 %
Global Bundle Error: 0.000 ft (US)

Bundle Error	
0.017 ft (US) X	
Overlap	Strength
3 % X	23 % X
Cloud-to-Cloud	Target Error



Max error of 0.066 ft (US).

Error greater than 0.066 ft (US).



Link Error Results

1 Overview

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 34	2024-2416 Cleveland Heights- Setup 002	2024-2416 Cleveland Heights- Setup 001	0 %	0.000 ft (US)
Link 35	2024-2416 Cleveland Heights- Setup 001	2024-2416 Cleveland Heights- Setup 004	0 %	0.000 ft (US)
Link 36	2024-2416 Cleveland Heights- Setup 003	2024-2416 Cleveland Heights- Setup 002	0 %	0.000 ft (US)
Link 37	2024-2416 Cleveland Heights- Setup 005	2024-2416 Cleveland Heights- Setup 003	0 %	0.000 ft (US)
Link 38	2024-2416 Cleveland Heights- Setup 006	2024-2416 Cleveland Heights- Setup 005	0 %	0.000 ft (US)
Link 39	2024-2416 Cleveland Heights- Setup 007	2024-2416 Cleveland Heights- Setup 006	52 %	0.017 ft (US)
Link 40	2024-2416 Cleveland Heights- Setup 008	2024-2416 Cleveland Heights- Setup 007	0 %	0.000 ft (US)
Link 41	2024-2416 Cleveland Heights- Setup 010	2024-2416 Cleveland Heights- Setup 008	7 %	0.000 ft (US)
Link 43	2024-2416 Cleveland Heights- Setup 010	2024-2416 Cleveland Heights- Setup 011	0 %	0.000 ft (US)
Link 44	2024-2416 Cleveland Heights- Setup 012	2024-2416 Cleveland Heights- Setup 011	0 %	0.000 ft (US)
Link 45	2024-2416 Cleveland Heights- Setup 009	2024-2416 Cleveland Heights- Setup 010	0 %	0.000 ft (US)
Link 42	2024-2416 Cleveland Heights- Setup 009	2024-2416 Cleveland Heights- Setup 019	0 %	0.000 ft (US)
Link 46	2024-2416 Cleveland Heights- Setup 012	2024-2416 Cleveland Heights- Setup 013	0 %	0.000 ft (US)
Link 47	2024-2416 Cleveland Heights- Setup 014	2024-2416 Cleveland Heights- Setup 013	0 %	0.000 ft (US)
Link 48	2024-2416 Cleveland Heights- Setup 015	2024-2416 Cleveland Heights- Setup 014	0 %	0.000 ft (US)
Link 49	2024-2416 Cleveland Heights- Setup 015	2024-2416 Cleveland Heights- Setup 016	0 %	0.000 ft (US)
Link 50	2024-2416 Cleveland Heights- Setup 021	2024-2416 Cleveland Heights- Setup 016	0 %	0.000 ft (US)
Link 51	2024-2416 Cleveland Heights- Setup 019	2024-2416 Cleveland Heights- Setup 018	0 %	0.000 ft (US)
Link 52	2024-2416 Cleveland Heights- Setup 016	2024-2416 Cleveland Heights- Setup 017	0 %	0.000 ft (US)
Link 53	2024-2416 Cleveland Heights- Setup 021	2024-2416 Cleveland Heights- Setup 020	0 %	0.000 ft (US)
Link 54	2024-2416 Cleveland Heights- Setup 017	2024-2416 Cleveland Heights- Setup 018	0 %	0.000 ft (US)

2 Details

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 34	2024-2416 Cleveland Heights- Setup 002	2024-2416 Cleveland Heights- Setup 001	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 35	2024-2416 Cleveland Heights- Setup 001	2024-2416 Cleveland Heights- Setup 004	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 36	2024-2416 Cleveland Heights- Setup 003	2024-2416 Cleveland Heights- Setup 002	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 37	2024-2416 Cleveland Heights- Setup 005	2024-2416 Cleveland Heights- Setup 003	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 38	2024-2416 Cleveland Heights- Setup 006	2024-2416 Cleveland Heights- Setup 005	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 39	2024-2416 Cleveland Heights- Setup 007	2024-2416 Cleveland Heights- Setup 006	52 %	0.017 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.017 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 40	2024-2416 Cleveland Heights- Setup 008	2024-2416 Cleveland Heights- Setup 007	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 41	2024-2416 Cleveland Heights- Setup 010	2024-2416 Cleveland Heights- Setup 008	7 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 43	2024-2416 Cleveland Heights- Setup 010	2024-2416 Cleveland Heights- Setup 011	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 44	2024-2416 Cleveland Heights- Setup 012	2024-2416 Cleveland Heights- Setup 011	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 45	2024-2416 Cleveland Heights- Setup 009	2024-2416 Cleveland Heights- Setup 010	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 42	2024-2416 Cleveland Heights- Setup 009	2024-2416 Cleveland Heights- Setup 019	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 46	2024-2416 Cleveland Heights- Setup 012	2024-2416 Cleveland Heights- Setup 013	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 47	2024-2416 Cleveland Heights- Setup 014	2024-2416 Cleveland Heights- Setup 013	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 48	2024-2416 Cleveland Heights- Setup 015	2024-2416 Cleveland Heights- Setup 014	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 49	2024-2416 Cleveland Heights- Setup 015	2024-2416 Cleveland Heights- Setup 016	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 50	2024-2416 Cleveland Heights- Setup 021	2024-2416 Cleveland Heights- Setup 016	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 51	2024-2416 Cleveland Heights- Setup 019	2024-2416 Cleveland Heights- Setup 018	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 52	2024-2416 Cleveland Heights- Setup 016	2024-2416 Cleveland Heights- Setup 017	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 53	2024-2416 Cleveland Heights- Setup 021	2024-2416 Cleveland Heights- Setup 020	0 %	0.000 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.000 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 54	2024-2416 Cleveland Heights- Setup 017	2024-2416 Cleveland Heights- Setup 018	0 %	0.000 ft (US)
		Cloud to Cloud		0.000 ft (US)
		Target	Mean Target Error:	--

Verify Summary

Graphics



2024-2416 Cleveland Heights-1