


Cyclone REGISTER 360 PLUS

Registration Report



Nov 13, 2024

Certified by:
Dan Boerner
Special Agent
Ohio BCI



2024-3564 OSHP OICI

Overall Quality

Error Results for Bundle 1

Setup Count: 12
Link Count: 11

Strength: 38 %
Overlap: 55 %
Global Bundle Error: 0.001 ft (US)


Bundle Error
0.025 ft (US) ✓

Overlap
55 % ✓

Strength
38 %

—

Error greater than 0.066 ft (US).



Link Error Results

1 Overview

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	2024-3564 OSHP OICI-Setup 001	2024-3564 OSHP OICI-Setup 002	62 %	0.011 ft (US)
Link 2	2024-3564 OSHP OICI-Setup 001	2024-3564 OSHP OICI-Setup 003	66 %	0.018 ft (US)
Link 3	2024-3564 OSHP OICI-Setup 003	2024-3564 OSHP OICI-Setup 004	61 %	0.006 ft (US)
Link 4	2024-3564 OSHP OICI-Setup 004	2024-3564 OSHP OICI-Setup 005	58 %	0.011 ft (US)
Link 5	2024-3564 OSHP OICI-Setup 005	2024-3564 OSHP OICI-Setup 006	67 %	0.011 ft (US)
Link 6	2024-3564 OSHP OICI-Setup 006	2024-3564 OSHP OICI-Setup 007	62 %	0.022 ft (US)
Link 7	2024-3564 OSHP OICI-Setup 007	2024-3564 OSHP OICI-Setup 008	32 %	0.032 ft (US)
Link 8	2024-3564 OSHP OICI-Setup 009	2024-3564 OSHP OICI-Setup 010	49 %	0.045 ft (US)
Link 9	2024-3564 OSHP OICI-Setup 010	2024-3564 OSHP OICI-Setup 012	50 %	0.037 ft (US)
Link 10	2024-3564 OSHP OICI-Setup 010	2024-3564 OSHP OICI-Setup 011	58 %	0.050 ft (US)
Link 11	2024-3564 OSHP OICI-Setup 008	2024-3564 OSHP OICI-Setup 009	41 %	0.034 ft (US)

2 Details

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	2024-3564 OSHP OICI- Setup 001	2024-3564 OSHP OICI- Setup 002	62 %	0.011 ft (US)
		Cloud to Cloud		0.011 ft (US)
		Target	Mean Target Error:	--

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 2	2024-3564 OSHP OICI- Setup 001	2024-3564 OSHP OICI- Setup 003	66 %	0.018 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.018 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 3	2024-3564 OSHP OICI- Setup 003	2024-3564 OSHP OICI- Setup 004	61 %	0.006 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.006 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 4	2024-3564 OSHP OICI- Setup 004	2024-3564 OSHP OICI- Setup 005	58 %	0.011 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.011 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 5	2024-3564 OSHP OICI- Setup 005	2024-3564 OSHP OICI- Setup 006	67 %	0.011 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.011 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 6	2024-3564 OSHP OICI- Setup 006	2024-3564 OSHP OICI- Setup 007	62 %	0.022 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.022 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 7	2024-3564 OSHP OICI- Setup 007	2024-3564 OSHP OICI- Setup 008	32 %	0.032 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.032 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 8	2024-3564 OSHP OICI- Setup 009	2024-3564 OSHP OICI- Setup 010	49 %	0.045 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.045 ft (US) --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 9	2024-3564 OSHP OICI- Setup 010	2024-3564 OSHP OICI- Setup 012	50 %	0.037 ft (US)
		Cloud to Cloud Target	Mean Target Error:	0.037 ft (US) --


Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 10	2024-3564 OSHP OICI- Setup 010	2024-3564 OSHP OICI- Setup 011	58 %	0.050 ft (US)
		Cloud to Cloud		0.050 ft (US)
		Target	Mean Target Error:	--

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 11	2024-3564 OSHP OICI- Setup 008	2024-3564 OSHP OICI- Setup 009	41 %	0.034 ft (US)
		Cloud to Cloud		0.034 ft (US)
		Target	Mean Target Error:	--

Verify Summary



2024-3564 OSHP OICI-1



ProjectIcon