

Cyclone REGISTER 360 PLUS

Registration Report



2025-2909

Sep 11, 2025


Certified by:

Michael Rostocil

Crime Scene Technician

Ohio Bureau of Criminal Investigation

Office of the Attorney General Dave Yost



Job 002

Overall Quality

Error Results for Bundle 1


Setup Count:	6
Link Count:	5
Strength:	79 %
Overlap:	19 %

Bundle Error
0 ft 5/16 in

Overlap

Strength

Global Bundle Error: 0 ft 1/16 in



Link Error Results

1 Overview

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	Job 002- Setup 001	Job 002- Setup 002	33 %	0 ft 1/4 in
Link 2	Job 002- Setup 004	Job 002- Setup 005	25 %	0 ft 5/16 in
Link 3	Job 002- Setup 005	Job 002- Setup 006	15 %	0 ft 5/16 in
Link 4	Job 002- Setup 003	Job 002- Setup 004	14 %	0 ft 3/8 in
Link 5	Job 002- Setup 002	Job 002- Setup 003	7 %	0 ft 1/2 in

2 Details

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	Job 002- Setup 001	Job 002- Setup 002	33 %	0 ft 1/4 in
Cloud to Cloud				0 ft 1/4 in
Target				Mean Target Error: --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 2	Job 002- Setup 004	Job 002- Setup 005	25 %	0 ft 5/16 in
Cloud to Cloud				0 ft 5/16 in
Target				Mean Target Error: --

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 3	Job 002- Setup 005	Job 002- Setup 006	15 %	0 ft 5/16 in
Cloud to Cloud				0 ft 5/16 in
Target				Mean Target Error: --


Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 4	Job 002- Setup 003	Job 002- Setup 004	14 %	0 ft 3/8 in
Cloud to Cloud				0 ft 3/8 in
Target		Mean Target Error:		--

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 5	Job 002- Setup 002	Job 002- Setup 003	7 %	0 ft 1/2 in
Cloud to Cloud				0 ft 1/2 in
Target		Mean Target Error:		--


Graphics



Job 002-2



2025 RTC NIST Pole 5 Feet.png



2025 RTC NIST Pole 15 Feet.png